U.S. ENVIRONMENTAL PROTECTION AGENCY



REGION X

IDAHO OPERATIONS OFFICE **422 WEST WASHINGTON STREET** BOISE, IDAHO 83702

July 22, 1988

Chris James, General Manager Cyprus Thompson Creek Mine P.O. Box 62 Clayton, Idaho - 83227

WATER COMPLIANCE SECTION EPA - REGION 10

JIII 25 1988

RE: NPDES Compliance Inspection

Permit No. ID-002540-2

Dear Mr. James:

Attached for your information are the results of an NPDES compliance inspection conducted at the Cyprus Thompson Creek Mine on May 25, 1988. Sample results verify compliance with current permit requirements.

The assistance of Mr. Doughty during the inspection was appreciated.

Sincerely,

Wally Scarburgh

Idaho Permits Coordinator

Enclosure

cc: Bob Braun, IDHW-DEQ, Boise Greg Kellogg, WD-135

BN0910B

1114	Status Environmental Protection Agent Washington, D. C. 20460	v -	Form Appr. ad .
			OMB No 2: - 3 0003
NPDES Co	NPDES Compliance Inspection Report		
	Section A: National Data System		Approval Ex 11-85
Transaction Code NPDES	yr/mo/day		ector Fac Type
1 25 3 200025402	11 12880512517	18년 19년	
	Remarks	ПППП	
Reserved Facility Evaluation Rating	BI QA 71 72 73	Reserved	
Name and Location of English Inspected	Section B: Facility Data	Entry Time A	Pormit Effective Date
Cyprus Mining Co Thompson C. P.O. Box 62	rec	Entry Time AM PM	1//~/
PARING CO. MONISTRE		Exit Time/Date	Pormit Expiration Date
11. 1 T/ 02		Exit Time/ Date	Commit expiration Date
Clay from Td. 83227 Name(s) of Orf-Site Representative(s)	Title(s)	L	Phone No(s)
wame(s) of Un-Site Representative(s)	1100(5)		Luoue Mo(2)
		N22 32W	
B. 1) /./.	C	Time I A	fairs 838-2200
Name, Address of Responsible Official	Supervisor E	Williamen Ind 14	Majors 838-2200
Charie There e	Carrel	Manager	
Chris Tames P.O. Box62	Phone No.	www.	Contacted
Clayten, Id. 83223		200	Yes No
	ection C: Areas Evaluated During I	The second secon	
	ory, M = Marginal, U = Unsatisfactor		
		patment S	Operations & Maintenance
G Records/Reports // Laborato		liance Schedules	Sludge Disposal
		Monitoring Program	Other:
3	y of Findings/Comments (Attach a		
<	See Attachmen	1	
	sec it incumen	9	MEG-
		(A)	CIEINABO
		الالالا	高配o介第111
		. 33	7)11
	* ;		JUL 25 1988
	· ·	Springer to the	
			COMPLIANCE SECTION
j			PA - REGION 10
2			
		*	a V
N 21 8			
Name(s) and Signature(s) of Inspectog(s)	Agency/Office/Telephone		Date
7	1 /	100000	//
Lann. MIN	EPA/200/554-1	450	5/25/88
			17 7
\$1(5)(1 112			
'Signature of Reviewer	Agency/Office	X III III	Date
	310/34/01/01		
	Regulatory Office Use Only	,	
Action Taken		Date	Compliance Status
			Noncompliance
No.		F = 1 \ \(\frac{1}{2} \) = 1	Compliance
EPA Form 3560-3 (Rev. 3-85) Previous editions are	obsolete.	Pes	V JS 07/25/88.1
		,00	

Records, Reports, and Schedules Checklist

A. Permit Verification

(YES NO N/A	INSPECTION OBSERVATIONS VERIFY INFORMATION CONTAINED IN PERMIT
	Yes No N/A	1. Correct name and mailing address of permittee.
(Yes No N/A	2. Facility is as described in permit.
	Yes No N/A	3. Notification has been given to EPA/State of new, different, increased discharges.
(Yes No N/A	4. Accurate records of influent volume are maintained, when appropriate.
(Yes No N/A	5. Number and location of discharge points are as described in the permit.
(Yes No N/A	6. Name and location of receiving waters are correct.
(Yes No N/A	7. All discharges are permitted.

		B. Recordkeeping and Reporting Evaluation	
(YES NO N/A	RECORDS AND REPORTS ARE MAINTAINED AS REQUIRED BY PERMIT	1
	Yes No N/A	 All required information is available, complete, and current; and Information is maintained for required period. Analytical results are consistent with the data reported on the DMR's. 	
	Yes No N/A	d. Results of analysis e. Dates of analysis	TION
4	Yes No N/A Yes No N/A	5. Monitoring records are adequate and include a. Flow pH, D.O., etc. as required by permit b. Monitoring charts	
(Yes No N/A	6. Laboratory equipment calibration and maintenance records are adequate.	
	Yes No N/A	d. Equipment supplies manual e. Equipment data cards	
		*Required only for facilities built with Federal construction grant funds.	

Records, Reports, and Schedules Checkinst

		$\overline{}$	
Yes	Nø	N/A	
Yes	No	N/A	
		N/A	
		N/A	

- 8. Pretreatment records are adequate and include:
 - a. Industrial Waste Ordinance (or equivalent documents)
 - b. Inventory of industrial waste contributors, including:
 - 1. Compliance records
 - 2. User charge information

Yes No N/A

9. SPCC properly completed, when required.

Yes No N/A

10. Best Management Practices Program available, when required.

C. Compliance Schedule Status Review

YES NO NA	THE PERMITTEE IS MEETING THE COMPLIANCE SCHEDULE
Yes No N/A	1. The permittee has obtained necessary approvals to begin construction.
Yes No N/A	2. Financing arrangements are complete.
Yes No N/A	3. Contracts for engineering services have been executed.
Yes No N/A	4. Design plans and specifications have been completed.
Yes No N/A	5. Construction has begun.
Yes No N/A	6. Construction is on schedule.
Yes No N/A	7. Equipment acquisition is on schedule.
Yes No N/A	8. Construction has been completed JUL 25 1988
Yes No N/A	9. Start up has begun. IPA - REGION 10
Yes No N/A	10. The permittee has requested an extension of time.
Yes No N/A	11. The permittee has met compliance schedule.

Records, Reports, and Schedules Checklist


D. POTW Pretreatment Requirements Review

YES NO N/A	THE FACILITY IS SUBJECT TO PRETREATMENT REQUIREMENTS	
	1. Status of POTW Pretreatment Program	
Yes No N/A	a. The POTW Pretreatment Program has been approved by EPA. (If not, is approva in progress?)	
Yes No N/A	b. The POTW is in compliance with the Pretreatment Program Compliance Schedule. (If not, note why, what is due, and intent of the POTW to remedy)	
	2. Status of Compliance with Categorical Pretreatment Standards.	
Yes No N/A	a. How many industrial users of the POTW are subject to Federal or State Pretreatment Standards?	
Yes No N/A	b. Are these industries aware of their responsibility to comply with applicable standards?	
Yes No N/A		
Yes No N/A	i. Have categorical industries in noncompliance (on BMR reports) submitted compliance schedules?	
Yes No N/A	ii. How many categorical industries on compliance schedules are meeting the schedule deadlines?	
Yes No N/A	d. If the compliance deadline has passed, have all industries submitted 90 day compliance reports?	
Yes No N/A	e. Are all categorical industries submitting the required semiannual report?	
Yes No N/A	f. Are all new industrial discharges in compliance with new source pretreatment standards?	
Yes No N/A	g. Has the POTW submitted its annual pretreatment report?	
Yes No N/A		
	1. Is the POTW conducting inspections of industrial contributors?	

Yes No N/A 3.

Are the industrial users subject to Prohibited Limits (403.5) and local limits more stringent than EPA in compliance?

(If not, explain why, including need for revision of limits.)




WATER COMPLIANCE SECTION EPA - REGION 10

.

Facility Site Review Checklis.

Yee No N/A	1. Standby power or other equivalent provision is provided.
Yes No N/A	2. Adequate alarm system for power or equipment failures is available.
Yes No N/A	 POTW handles and disposes of sludge according to applicable Federal, State, and and local regulations.
Yes No N/A	4. All treatment units, other than back up units, are in service.
Yes No N/A	5. Procedures for facility operation and maintenance exist.
Yes No N/A	6. Organization plan (chart) for operation and maintenance is provided.
No N/A	7. Operating schedules are established.
Yes No N/A	8. Emergency plan for treatment control is established.
Yes No N/A Yes No N/A Yes No N/A	9. Operating management control documents are current and include: a. Operating report b. Work schedule c. Activity report (time cards)
Yes No N/A	b. Shop drawings c. Construction specifications
Yes No N/A	11. Adequate number of qualified operators are on-hand.
Yes No N/A	12. Established procedures are available for training new operators.
Yes No N/A	 Adequate spare parts and supplies inventory and major equipment specifications are maintained.
Yes No N/A	14. Instruction files are kept for operation and maintenance of each item of major equipment.
Yes No N/A	15. Operation and maintenance manual is available.
Yes No N/A	16. Regulatory agency was notified of by passing. (Dates)



WATER COMPLIANCE SECTION EPA - REGION 10

Facility Site Review Checklist

Yes No N/A	17. Hydraulic and/or organic overloads are experienced. Reasons for overloads
Yes No N/A	18. Up to date equipment repair records are maintained.
Yes No N/A	19. Dated tags show out of service equipment.
Yes No N/A	20. Routine and preventive maintenance are scheduled/performed on time.

Penulttee Sampling Inspection Checklist

A. Permittee Sampling Evaluation

1. Samples are taken at sites specified in permit.
2. Locations are adequate for representative samples.
3. Flow proportioned samples are obtained where required by permit.
4. Sampling and analysis completed on parameters specified by permit.
5. Sampling and analysis done in frequency specified by permit.
6. Permittee is using method of sample collection required by permit. Required Method: () va / If not, method being used is: () Grab () Manual composite () () Automatic composite
7. Sample collection procedures are adequate: a. Samples refrigerated during compositing become used become and sample holding times before analyses conform with 40 CFR 136.3
8 Monitoring and analyses are performed more often than required by permit. If so, results reported in permittee's self-monitoring report.

B Sampling Inspection Procedures and Observations

Yes No N/A	1. Grab samples obtained.
res No N/A	2. Composite sample obtained Compositing frequency Preservation
res No N/A	3. Sample refrigerated during compositing.
les No N/A	4. Flow proportioned sample obtained.
es No N/A	5. Sample obtained from facility sampling device.
es No N/A	6. Sample representative of volume and nature of discharge.
es No N/A	7. Sample split with permittee.
es No N/A	8. Chain of custody procedures employed.

EGEIVED JUL 25 1988

WATER COMPLIANCE SECTION EPA - REGION 10

Yes	No	N/A
Yes	No	N/A
Yes	No	N/A
Yes	No	N/A
Yes	No (N/A
Yes	No	N/A
	Yes Yes	Yes No Yes No Yes No Yes No


Yes

- 1. Primary flow measuring device is properly installed and maintained.
- 2. Flow records are properly kept.
- 3. Sharp drops or increases in flow values are accounted for.
- 4. Actual flow discharged is measured.
- 5. Influent flow is measured before all return lines.
- 6. Effluent flow is measured after all return lines.
- Secondary instruments (totalizers, recorders, etc.) are properly operated and maintained.
- 8. Spare parts are stocked.

B. Flow Measurement Inspection Checklist - Fluxes

Yes	No	N/A
Yes	No	N/A

- Flow entering flume appears reasonably well distributed across the channel and free of turbulence, boils, or other distortions.
- 2. Cross-sectional velocities at entrance are relatively uniform .
- 3. Flume is clean and free of debris or deposits.
- 4. All dimensions of flume are accurate.
- 5. Side walls of flume are vertical and smooth.
- 6. Sides of flume throat are vertical and parallel.
- 7. Flume head is being measured at proper location.
- 8. Measurement of flume head is zeroed to flume crest.
- 9. Flume is of proper size to measure range of existing flow.
- 10. Flume is operating under free-flow conditions over existing range of flows.



WATER COMPLIANCE SECTION EPA - REGION 10

			C Vice Vocarron - 7	-017 (313) 101
			C. Flow Measurement Inspection Checklist - Wien	門の回の日の一位
				- Lu 07 1000 E
V	-noi	che	1. What type of weir is being used?	DESTRUCTION OF THE PROPERTY OF
Yes	No	N/A	2. The weir is exactly level.	EPA - REGION 10
Yes)	No	N/A	3. The weir plate is plumb and its top edges are sharp a	and clean.
Yes)	No	N/A	4. There is free access for air below the nappe of the v	weir.
Yes	No	N/A	 Upstream channel of weir is straight for at least for level, and free from disturbing influences. 	ur times the depth of water
Yes	No	N/A	6. The stilling basin of the weir is of sufficient size	and clear of debris.
Yes	No	N/A	7. Head measurements are properly made by facility person	ornel.
Yes	No	N/A	8. Proper flow tables are used by facility personnel.	
		\neg	1. Type of flowmeter used:	
		\exists	2. What are the most common problems that the operator I	has had with the flowneter?
			3. Measured Wastewater flow: mgd; Recorded	flow:
	15		4. Design flow:mgd.	
Yes	No	N/A	5. Flow totalizer is properly calibrated.	
			6. Frequency of routine inspection by proper operator:	/day.
			7. Frequency of maintenance inspections by plant person	nel:/year.
			8. Frequency of flowmeter calibration: /mon	th.
Yes	No	N/A	9. Flow measurement equipment adequate to handle expected	d ranges of flow rates.
	No	N/A	10. Venturi meter is properly installed and calibrated.	
Yes				

Laboratory	Quality	Assurance	Checklist
------------	---------	-----------	-----------

A. General

RECEIL

TE No N/A

1. Written laboratory quality assurance manual is available.

JUL 25 1988

B . Laboratory Procedures

WATER COMPLIANCE SECTION EPA-REGION 10

	7.64
Yes No N/A	1. EPA approved analytical testing procedures are wood.
Yes No N/A	2. If alternate analytical procedures are used, proper approval has been obtained.
Yes No N/A	3. Calibration and maintenance of instruments and equipment is satisfactory.
Yes No N/A	4. Quality control procedures are used.
Yes No N/A	5. Quality control procedures are adequate.
	6. Duplicate samples are analyzed % of time.
	7. Spiked samples are used% of time.
Yes No N/A	8. Commercial laboratory is used Name Analytical Caboratories
*	Address
	Contact
	Phone

C. Laboratory Facilities and Equipment

1. Proper grade distilled water is available for specific analysis.
2. Dry, uncontaminated compressed air is available.
3. Fune hood has enough ventilation capacity.
4. The laboratory has sufficient lighting.
5. Adequate electrical sources are available.
6. Instruments/equipment are in good condition.
7. Written requirements for daily operation of instruments are available.

.ab bory Quality Assurance Checklist , ont. ed)

C. Laboratory Facilities and Equipment (continued)

Yes No N/A	8. Standards are available to perform daily check procedure.
Yes No N/A	9. Written trouble shooting procedures for instruments are available.
Yes No N/A	10. Schedule for required maintenance exists.
Yes No N/A	11. Proper volumetric glassware is used.
Yes No N/A	12. Glassware is properly cleaned.
Yes No N/A	13. Standard reagents and solvents are properly stored.
Yes No N/A	14. Working standards are frequently checked.
Yes No N/A	15. Standards are discarded after recommended shelf life has expired.
Yes No N/A	16. Background reagents and solvents run with every series of samples.
Yes No_N/A	17. Written procedures exist for cleanup, hazard response methods, and applications of correction methods for reagents and solvents.
Yes No N/A	18. Gas cylinders are replaced at 100-200 psi.

D. Laboratory's Precision, Accuracy, and Control Procedures

Yes No N/A	 A minimum of seven replicates is analyzed for each type of control check and this information is on record.
Yes No N/A	 Plotted precision and accuracy control charts are used to determine whether valid, questionable, or invalid data are being generated from day to day.
Yes No N/A	Control samples are introduced into the train of actual samples to ensure that valid data are being generated.
Yes No N/A	4. The precision and accuracy of the analyses are good.

EGETTED JUL 25 1988

VVATER COMPLIANCE SECTION EPA - REGION 10

Lawratory Quality Assurance Checklist (Continued)

E. Data Handling and Reporting

Yes No N/A	1. Round-off rules are uniformly applied.							
Yes No N/A	2. Significant figures are established for each analysis .							
Yes No N/A	3. Provision for cross-checking calculation is used							
Yes No N/A	4. Correct formulas are used to reduce to simplest factors for quick, correct calculation							
Yes No N/A	5. Control chart approach and statistical calculations for quality assurance and report are available and followed							
res No.N/A	6. Report forms have been developed to provide complete data documentation and permanent records and to facilitate data processing							
es No N/A	7. Data are reported in proper form and units							
les No N/A	8. Laboratory records are kept readily available to regulatory agency for required period of time							
Yes No N/A	9. Laboratory notebook or preprinted data forms are permanently bound to provide good documentation							
res No N/A	10. Efficient filing system exists enabling prompt channeling of report copies							

F. Laboratory Personnel

Yes No N/A	1. The analyst has appropriate training	8.0	
Yes No N/A	2. The analyst follows the specified procedures	11.2	
Yes No N/A	3. The analyst is skilled in performing analyses		

RECEIVED JUL 25 1988

WATER COMPLIANCE SECTION
IPA-REGION 10

	Teaser =	T			1.		5 14-4-3
	SAMPLE MEASUREMENT				00	/	*/
	PERMIT .						
75 5	SAMPLE MEASUREMENT			6			
mglo	PERMIT REQUIREMENT		4	30			
Rec.	SAMPLE MEASUREMENT			6.010			
ng/f	PERMIT			,49			
F. Rec.	SAMPLE MEASUREMENT			6.001			
nole	PERMIT REQUIREMENT		-	10053			
Rec.	SAMPLE MEASUREMENT			6,010			*
Cu/D	PERMIT REQUIREMENT			10245			
Rec.	SAMPLE MEASUREMENT		1	6.003			-
18/10	PERMIT		,	,0150		<i>' ;</i>	* *
Rac.	SAMPLE MEASUREMENT		3	£.0005		~	
9/2	PERMIT REQUIREMENT			non-det.	DECENTION.		
, Rec.	SAMPLE MEASUREMENT			,027	ال نائل ا	JL 25 1988	3
2n 48/8	PERMIT REQUIREMENT			,163		MPLIANCE S	
0	SAMPLE MEASUREMENT				lei'/	A - REGION TO	
8	PERMIT REQUIREMENT						
TFALL NO.	OIL SHEEN '	GREASE	TURBIDITY	VISIBLE FOAM	VISIBLE FLOAT SOL	COLOR	OTHER
201	NONY	LOUP	nonr	none	noug	nong	MONG-
				-	,		
TION M - Se-	npling Inspection Pro			propriate for sampli			FIRE III
/	PLES OBTAINED	9		•			
	E OBTAINED						
FLOWPRO	PORTIONED SAMP	LE	,				
	IC SAMPLER USED			,		+	
	PLIT WITH PERMIT						
	CUSTODY EMPLOY					59	
	BTAINED FROM FA	ACILITY SAMPL	ING DEVICE		ERVATION		2
	REQUENCY		DYES	□NO PRESI	ERVATION		
			LIVEC	I I DICE			

		September 200		¬	1.	1*.		
-	SAMPLE MEASUREMENT	r	-1		002			
	PERMIT				(*)	2		
	SAMPLE MEASUREMENT	г		Lz				
735	PERMIT REQUIREMENT	8	6	30		. S		
T. Rec.	SAMPLE MEASUREMENT	r		6,010		\$8		
Male	PERMIT REQUIREMENT			,49				
T.Rec.	SAMPLE MEASUREMENT	-		2.001		Ø9		
Cd. 10	PERMIT REQUIREMENT			10053	3			
T. Ree.	SAMPLE MEASUREMENT			6,010			4	
Can	PERMIT	1		10245	_			
T. Rec.	SAMPLE MEASUREMENT		-	6003	3	· ·		
Pb./0	PERMIT		,	10150			· ·	
T. Rec.	SAMPLE MEASUREMENT		.9	60005	-	32		
MAIR	PERMIT REQUIREMENT			non-det.				
T. Rec.	SAMPLE MEASUREMENT		4	.014	/			
2n.	PERMIT REQUIREMENT			,163			200	
0	SAMPLE MEASUREMENT					Ø # 5		
	PERMIT REQUIREMENT	* 5	1976					
UTFALL NO.	OIL SHEEN	GREASE	TURBIDITY	VISIBLE FOAM	VISIBLE FLOAT SOL	COLOR	OTHER	
002	None	None	nono	NOMP	none	doup	none	
						92		
		(Sections M and	N: Complete as ap	propriate for samp	ling inspections)		1	
CTION M - San	npling Inspection Pr							
GRAB SAN	APLES OBTAINED	19			50	DECE	I VER	
	E OBTAINED	PLE			. (5	3	')!/	
	TIC SAMPLER USE				4	JUL 2	5 1988	
	PLIT WITH PERMIT				321 WS	Secretarian vents		
CHAIN OF	CUSTODY EMPLO	YED	ING DEVICE		\VA	TER COMPLI		
POR MANUFACTOR OF THE PARTY OF	REQUENCY		occur vita una cicario e constitu	PRES	SERVATION		0)	
	SERATED DURING	COMPOSITING:	☐ YES	□ио ·				
	SENTATIVE OF VO			RGE 4725				